Page 1 of Page(s)								ge(s)	
1. Originator	2. Log Date:	3. CCR #:		4. Rev	: 5. Tel:	5. Tel:		7. Org.	
Sarah Lewallen	01/07/04	04-0005		_	301-925-0865		3103A	COTS	
8. CCR Title: Upgrade the datapool hosts at GSFC, NSIDC, LaRC, and EDC									
9. Originator Signature/Date			10. Class		11. Type:		<b>12. Need Date:</b> 1/30/04		
Sarah Lewallen /s/ 01/06/04			II		CCR				
13. CCR Sponsor Signature/Date			14. Category of		CII : DI : 1 0-7)				
Peter T. Gilruth /s/ 01/06/04				Update ECS/EMD Baseline Do			Routine		
16. Documentation/Drawings Impacted (Review and submit checklist): 920-TDG-001, 920-TDE-001, 920-TDL-001, 920-TDN-001				edule 18. CI(s) Affected:DPSHW					
19. Release Affected by this Change: 20. Date due			to Custo	omer:		21. Estimated Cost:			
N/A			Tack Da		e - Under 100K				
22. Source Reference: ☐NCR (attach) ☐Action Item ☐Tech Ref. ☐GSFC ☐Other: Synergy IV									
23. Problem: (use additional Sheets if necessary) Need additional processing power in the SUN 4800 systems used as datapool.									
, 3, 3, 3, 3, 3, 3, 3, 3, 3, 3, 3, 3, 3,									
24. Proposed Solution: (use additional sheets if necessary)									
Add additional CPUs and memory to the SUN 4800. Add 4 $\times$ 1050 MHz CPUs and 8 GB of memory to LaRC and EDC.									
Remove 4x900 MHz CPUs and 4 GB of memory and replace with 4 x 1050 MHz CPUs and 8 GB of memory.  Add 4 x 900 MHz CPUs and 4 GB of memory at NSIDC (reuse from GSFC).									
25. Alternate Solution: (use additional sheets if necessary) None									
26. Consequences if Change(s) are not approved: (use additional sheets if necessary)									
Will not be able to meet processing requirements for Synergy.									
27. Justification for Emergency (If Block 15 is "Emergency"):									
28. Site(s) Affected: ☐EDF ☐PVC ☐VATC ☐EDC ☐ GSFC ☐LaRC ☐NSIDC ☐SMC ☐AK ☐JPL									
□ EOC □ IDG Test Cell □ Other  29. Board Comments:			30. Work Assigned			ned To	To: 31. CCR Closed Date:		
					9-				
22 SCDV CCB Chair (Cian	(Data):			A :: . / C	D'		VACAL: -1:: -	-4/E0DIO EDD	
32. SCDV CCB Chair (Signa Byron Peters /s/ 1/8/04	Date).	isposition: A	pproved wd/ECS	App/C	om. Disappi	ovea	vvitnaraw FW	/d/ESDIS ERB	
33. EDF CCB Chair (Sign/D	eate): D	اع Sisposition: Ap		App/Co	om. Disapo	roved	Withdraw Fw	d/ESDIS ERB	
·····	,	•	wd/ECS	F 14. 3.					
34. ECS CCB Chair (Sign/D	Pate): Dis	<b>sposition:</b> Ap		App/Co	m. Disapp	roved	Withdraw Fv	vd/ESDIS ERB	
		Fw							

CM01JA00 Revised 10/2/03 ECS/EDF/SCDV

## ADDITIONAL SHEET

CCR #: 04-0005 Rev: — Originator: Sarah Lewallen

**Telephone:** 301-925-0865 **Office:** 3103A

Title of Change: Upgrade the datapool hosts at GSFC, NSIDC, LaRC, and EDC

In preparation for the update, the following patches are needed:

5.13.x - 112494 5.14.x - 112883 5.15.x - 112884

\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*

\*WARNING! DO NOT INSTALL CPUS UNTIL THE FIRMWARE IS UPDATED!\*

Expand these in the /tmp directory of your ftp server. Read over the install.info document. The commands needed to update the firmware are found in this document. The firmware will be updated on SC1 first (in incremental steps) from the remote ftp server. Once SC1 is up to 5.15.1, the SC0 will be flashed from SC1. Then the new CPUs may be added. If you put the CPUs in first, the service flag will be triggered since the firmware on the system controller can't communicate with the CPUs and it causes lots of headaches.

The DAAC should schedule Sun to do the CPU install. If there is any question about the firmware upgrade, the DAAC may request a Sun tech to do upgrade prior to the CPU installation. Be sure to include this request in the ticket so the Sun tech will be prepared with a laptop, a null modern cable, and a cross connect RJ45.

For additional questions, call Sarah Lewallen 301-925-0865.

CM01AJA00 Revised 10/2/03 ECS/EMD